

**Arlington Housing Authority**  
 Department of Housing and Community Development  
 Inspection Checklist State Funded Program

Inspection Date: 1/26/12

Inspector: Joe D'Addo

Resident: Peter Szento

Results: Pass O Yes---No Comments: \_\_\_\_\_

Address: 1104

Pets: \_\_\_\_\_ Auto: \_\_\_\_\_

Winslow Chestnut Hauser Drake Cottages Cusack Condo \_\_\_\_\_ Other \_\_\_\_\_

Item#	Room	P	F	Comments	Item#	Room	P	F	Comments			
<b>Living Room</b>					<b>Bedroom</b>							
L2 Security/ Door					B2 Security/Door							
L3 Ceiling					B3 Ceiling							
L4 Walls					B4 Walls							
L5 Floor					B5 Floor							
L6 Electrical					B6 Electrical							
L7 Windows/Scn					7B Window/Scn.							
<b>Kitchen</b>					<b>Heating</b>							
K2 Security/Entry					H1 Adequacy							
K3 Ceiling					H2 Fuel Storage							
K4 Walls					H3 Condition/Safety							
K5 Floor					H4 Air Conditioning							
K6 Electrical					<b>Plumbing</b>							
K7 Window/scn					P1 Water Pressure							
K8 Sink					P2 Water Heater							
K9 Stove /range/oven					P3 Water temperature							
K10 Refrigerator					P4 Plumbing/Piping							
K11 Dishwasher/Disp.					P5 Sewer/Septic							
K12 Cabinets/Ctr.tops					P6 Washer/Dryer							
<b>Bathroom</b>					<b>General Health &amp; Safety</b>							
BA2 Security/Door					G1 Access/egress/security							
BA3 Ceiling					G2 Interior Halls/Stairs							
BA4 Walls					G3 Garbage/debris							
BA5 Floor					G4 Infestation							
BA6 Electrical					G5 Paint Condition							
BA7 Window/scn/vent					G6 Electrical							
BA8 Toilet					G7 Smoke & Carbon Det.							
BA9 Sink					G8 Emergency Lighting							
BA10 Tub/Shower					G9 Sprinklers							
Exterior					G10 Elevator							
X1 Roof					G11 Interior Air Quality							
X2 Drainage					G12 Dampness/wet							
X3 Roof Fans					G13 Interior Hazards							
Remarks:					G14 Vial of Life	Yes	-----	No	Pull Alarm	Yes	-----	No

OK